Template for Evidence(s)
UI GreenMetric Questionnaire

University   : IFSULDEMINAS
Country   : BRAZIL
Web Address   : https://www.ifsuldeminas.edu.br/index.php

[1] Setting and Infrastructure (SI)

[1.22] Security and Safety Facilities

Figure 1: Machado Campus 360° monitoring camera.

Figure 2: Machado Campus security ordinance.

Figure 3: Machado Campus CCTV in entrance.

Figure 4: Pouso Alegre Campus CCTV.

Figure 5: Pouso Alegre Campus emergency lights.

Figure 6: Pouso Alegre Campus fire alarm, fire extinguisher and hydrant.

Figure 7: Pouso Alegre Campus security camera.

Figure 8: Pouso Alegre fire alarm and fire extinguisher.

Figure 9: Rectory fire alarm and hydrant.

Figure 10: Rectory fire alarm and fire extinguisher.

Figure 11: Inconfidentes Campus ordinance establishing the fire brigade.


Figure 12: Inconfidentes Campus panic button on the toilet for people with special needs.

Figure 13: Inconfidentes Campus CCTV.

Figure 14: Rectory ordinance establishing the fire brigade.

Figure 15: Inconfidentes Campus accommodation
certified by the Fire Department.

Description

All nine IFSULDEMINAS units have safety and security facilities, which include alarm systems, security monitoring systems and fire fighting systems. The accessibility facilities and the small size of the buildings allow for quick evacuation in less than 10 minutes. Source: IFSULDEMINAS.